



## Goat garden in Brenna

### Accessibility card

#### Basic information

 Brenna, ul. Sportowa 3, 43-438  
GPS: N 49.7198995, E 18.9221203

 +480 513 422 143  
 [koziagroda@onet.pl](mailto:koziagroda@onet.pl)  
 <http://www.koziagroda.com/>

#### Description

A place that spreads the culture of the Silesian Beskids. A renovated building in which are workshops and regional cuisine on offer. In the vicinity of the building is a pen, where goats, sheep, geese and hens are kept. Regional events are held here, including bread and cheese production workshops, demonstrations of baking patties (traditional Silesian potato pancakes), rams on fire, etc. Workshops for schools and kindergartens, training sessions and exhibitions are also organized.

#### Accessibility

##### Entrance

- ❖ Access pavement leading to the entrance to the building is wheelchair accessible (without stairs, curbs, height differences and gaps greater than 2 cm), min. 150 cm wide, narrowing max. to 90 cm, solid but uneven surface, material: gravel and grass.
- ❖ There are 2 entrances to the building. At the side entrance there are 2 steps, at the main entrance there is a wooden ramp (width 150 cm, length 400 cm, height 30 cm) without handles.
- ❖ The entrance door has a sufficiently large area (150x150 cm), without slopes.
- ❖ Entrance doors are min. 90 cm wide and the threshold is max. 2 cm. The door opens inwards.

##### Interior premises

- ❖ All pathways in the building are min. 150 cm wide.
- ❖ All doors and passages are min. 80 cm wide.
- ❖ The surface of the paths is firm and not slippery - wooden floors.
- ❖ The thresholds / steps are not more than 2 cm high.
- ❖ There is a sufficient area for the movement of persons in a wheelchair or a pram.
- ❖ There are seating areas.
- ❖ Most exhibits can be touched.

##### Exterior premises

- ❖ In the outdoor area there is an animal enclosure, a picnic area with a fireplace (former shed).
- ❖ The entrance to the outdoor area is wheelchair accessible.
- ❖ The outdoor areas are level to slightly undulating terrain (with a longitudinal slope of up to 6%).
- ❖ Outdoor terrain surface: grass, gravel, uneven and unstable surface.

- ❖ In the outdoor area there are information and orientation signs in Polish, which are easy to read and understand.

---

### Accessible toilet

---

- ❖ The facility has wheelchair accessible toilet.
- ❖ Cabin entrance door is min. 80 cm wide.
- ❖ The door opens outwards (from the cabin).
- ❖ The cabin has dimensions of min. 160x160 cm.
- ❖ Next to the toilet there is a free space for a wheelchair (at least 90 cm wide), which does not interfere with any equipment (waste bin, sink, changing table, etc.).
- ❖ There are no handles in the toilet.

---

### Services and equipment

---

- ❖ Parking is available without reserved parking spaces.
- ❖ The visit is possible without a prior arrangement.
- ❖ Guide and registered support dogs are permitted entry.
- ❖ Induction loops are not installed in the object.
- ❖ Special educational programs for children and a natural playground available.

*Date of processing: 2/2019*